SEP 0 6 2005- W

10/714,760

cope

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.

6,864,569 B2

Issue Date

March 8, 2005

Certificate

Inventor

Paul Evans

SEP 1 2 2005

of Correction

Docket No.

858063.458C1

Date

August 30, 2005

Mail Stop Certificate of Correction Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents:

A certificate of correction is respectfully requested in the above-identified patent. The following errors have been made:

Claim 10 contains two errors; 1) column 10, line 41, "a set or pins" was incorrectly changed from --a set of pins--in line 4 of Claim 11 as amended on September 27, 2004, 2) column 10, line 58, "conductive trucks" was incorrectly changed from --conductive tracks-- in line 16 of claim 11 as amended on September 27, 2004. Please note, due to claim canceling and renumbering Claim 11 has become Claim 10 in the issued patent.

Claim 11, column 10, line 67, "set or topside circuit components." was incorrectly changed from --set of topside circuit components.-- in line 2 of Claim 12 as filed on November 17, 2003. Please note, due to claim canceling and renumbering Claim 12 has become Claim 11 in the issued patent.

Claim 25, column 13, line 12, "a multiplexer" was incorrectly changed from --a multiplexor-- in line 19 of Claim 29 as filed on September 27, 2004. Please note, due to claim canceling and renumbering Claim 29 has become Claim 25 in the issued patent.

Attached is form PTO/SB/44, which indicates the corrections to be made, by reference to the column and line numbers in the printed patent. Because the errors were made by

the Patent Office, no fee is necessary. However if they are determined to be our errors, the Commissioner is hereby authorized to charge payment of any fees associated with this communication to Deposit Account No. 19-1090.

Respectfully submitted,
SEED Intellectual Property Law Group PLLC

E. Russell Tarleton
Registration No. 31,800

Enclosures:

Form PTO/SB/44 Postcard

SEED Intellectual Property Law Group PLLC 701 Fifth Avenue, Suite 6300 Seattle, Washington 98104-7092 Phone: (206) 622-4900

Fax: (206) 682-6031

685153

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO

: 6,864,569 B2

DATED

: March 8, 2005

INVENTOR

: Paul Evans

It is certified that errors appear in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 10,

Line 41, "a set or pins" should read as --a set of pins--.

Line 58, "conductive trucks" should read as --conductive tracks--.

Line 67, "set or topside circuit components." Should reads as --set of topside circuit components.--."

Column 13,

Line 12, "a multiplexer" should read as --a multiplexor--.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,864,569 B2

E. Russell Tarleton
Seed Intellectual Property Law Group PLLC
701 Fifth Avenue, Suite 6300
Seattle, Washington 98104

No. of additional copies

Page 1 of 1

Burden hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.